GOVERNMENT OF INDIA
URBAN DEVELOPMENT AND POVERTY ALLEVATION
LOK SABHA

UNSTARRED QUESTION NO:5394
ANSWERED ON:30.04.2002
PAINTING OF IRON GATES IN GOVERNMENT QUARTERS
SHEESH RAM SINGH RAVI

Will the Minister of URBAN DEVELOPMENT AND POVERTY ALLEVATION be pleased to state:

to the answer given to USQ No. 5384 dated 28.8.2001 and state:

(a): whether the CPWD is not painting theiron gates provided on 10 per cent payment in Government Quarters inthe Government colonies in New Delhi at regular intervals despite requests from the allottees;

(b): if so, the reasons therefor;

(c): whether the CPWD is not putting pucca boundry wallsand then fixing the barbed wires upon them raising the height to a level not to be jumped by any intruder and no steel sheets are affixed with the gates for privacy in the iron gates provided on 10 per cent charges;

(d): if so, the reasons therefor;

(e): the measures taken by the Government in this regard; and

(f): the number of loft tanks cleaned in the colonies, during each of the last three years, colony-wise?

Answer

MINISTER OF STATE IN THE MINISTRY OF URBAN DEVELOPMENT & POVERTY ALLEVIATION (SHRI BAN DATTATREYA)

(a)&(b): Iron gates fixed on payment of 10% are painted regularly subject to availability of funds.

(c)&(d): Pucca boundary walls with barbed wire fencing/grill are provided around houses of persons who have been given security cover by Ministry of Home Affairs. Similarly, boundary walls are being constructed around various Government colonies as a security measure.

Iron gates are provided along with fencing for lawns but no steel sheets are fixed on them. Neither there is any provision for fixing such sheets nor would this be advisable both economically and aesthetically.

(e): Does not arise in view of (c) & (d) above.

(f): As per Annexure attached.

ANNEXURE

ANNEXURE REFERRED TO IN REPLY TO PART (f) OF LOK SABHA USQ NO.5394 FOR 30.4.2002.

Details of Loft Tanks Cleaned during the last three years colony-wise.

Sl.No.	Name of Colony	No. of tanks Cleaned during			Remarks
		98-99	99-2000	2000-01	
1.	Sector I DIZ Area (i/c Albert Square)	-	52 Nos.	70 Nos.	
2.	Sector II DIZ Area (K.B.Marg, Peshwa Road(J,K & H	-	305 Nos.	443 Nos.	

Block)

3.	Secor III DIZ Area (`E` Pocket)	-	10 Nos.	20 Nos.	
4.	M.S. Flats Peshwa Road & K.B. Marg	-	60 Nos.	107 Nos.	
5.	Hanuman Road	-	20 Nos.	20 Nos.	
6.	`D` Sector DIZ Area	-	165 Nos.	252 Nos.	
7	B.K.S. Marg	-	93 Nos.	141 Nos.	
8.	Timarpur	-	-	11 Nos.	
9.	Minto Road Complex	-	-	4 Nos.	
10.	Aram Bagh	-	170 Nos.	190 Nos.	
11.	Mohd.Pur Govt. Colony	-	-	-	
12.	Vasant Vihar Govt. Colony	-	500 Nos.	-	
13.	R.K. Puram (Sector 1 to 13)	294 Nos.	1237 Nos.	1722 Nos.	
14.	Netaji Nagar	450 Nos.	272 Nos.	120 Nos.	
15.	Chankya Puri	-	-	-	
16.	North West Moti Bagh	100 Nos.	-	79 Nos.	
17.	Moti Bagh-I	380 Nos.	280 Nos.	700 Nos.	
18.	I.B. Colony, Bapu Dham	50 Nos.	-	50 Nos.	
19.	Nanak Pura	325 Nos.	400 Nos.	400 Nos.	
20.	Lodhi Colony	1050 Nos.	1050 Nos.	1300 Nos.	
21.	Lodhi Road Complex	10 Nos.	25 Nos.	30 Nos.	
22.	Nauroji Nagar	-	-	140 Nos.	
23.	Sarojini Nagar	-	-	660 Nos.	
24.	Laxmi Bai Nagar	150 Nos.	220 Nos.	1080 Nos.	
25.	Kidwai Nagar	226 Nos.	414 Nos.	598 Nos.	
26.	Sriniwaspuri	NA	NA	30	Loft Tanks provided in year 2000
27.	Asiad Village Complex	4	4	4	